

Material Safety Data Sheet

Identify: **WestLube**

Section I

Manufacture: Anchor Chemical Company

Distributed By: Westland Products, PO Box 2378, Morgan Hill, CA 95038. 888-475-5440

Address: 777 Canterbury Rd
Westlake, OH. 44145

Emergency Telephone Number: 440-871-1660

Information Telephone Number: 440-871-1660

Date Prepared 1/4/2002

HMIS Ratings:

Health: 1
Fire: 0
Reactivity: 0
Personal Protection: A

Section II - Hazardous Ingredients/Identity Information

None

NO MATERIAL ITEMS ARE TO BE FOUND IN ANY STATES RTK LIST
THIS MATERIAL SHOULD BE CONSIDERED NON-HAZARDOUS
THIS IS A NON-CONTROLLED MATERIAL

SECTION III - Physical/Chemical Characteristics

Boiling Point: 225 F

Specific Gravity: (H₂O=1) 1.0365

Vapor Pressure: (mm Hg) N/A

Melting Point: N/A

Vapor Density: (Air = 1) N/D

Evaporation Rate: (Butyl Acetate = 1) N/D

Solubility in Water: Dispersible

Appearance and Odor: Green semi-paste with lemony odor

Section IV - Fire and Explosion Hazard Data

Flash Point (Method Used) None

Flammable Limits: LEL: N/A UEL: N/A

Extinguishing Media: N/A

Special Fire Fighting Procedures: None Noted

Unusual Fire & Explosion Hazards: None Noted

Section V - Reactivity Data

Stability: Stable

Conditions to avoid: None known

Incompatibility (materials to avoid) None known

Hazardous Decomposition or by-products: None known

Hazardous polymerization: Will not occur

Section VI - Health Hazard Data

Route (s) of Entry: Eyes, Skin, inhalation and ingestion

Health Hazards (Acute and Chronic)

Eyes: Will cause irritation on contact

Inhalation: Inhaling would be a highly unusual happening; however, smoke from welding parts with WestLube heavy residue may cause minor irritation to the throat.

Ingestion: Will cause Nausea because of the soap base.

Signs and Symptoms of Exposure:

Eyes: Entry into the eye will cause stinging and reversible redness of the conjunctive tissue.

Skin: Some prior skin conditions may be aggravated temporarily. If some animal base soaps irritate WestLube may irritate skin.

Inhalation: Mist may irritate mucous membranes

Ingestion: Will cause nausea.

Medical Conditions generally aggravated by exposure: None noted

Emergency and first aid procedures:

Eyes: Wash with copious amounts of water for at least 15 minutes. Seek medical attention.

Skin: Wash exposed areas with soap and water.

Section VII - Precaution for Safe Handling and Use

Steps to be taken in case material is released or spilled: If possible, return as much as possible to, soak up balance with clay and dispose in sanitary landfill. Small amounts may be flushed into sanitary sewer.

Waste disposal method: Sanitary landfill or small amount may be disposed in to sanitary sewer.

Precautions to be taken when handling and storing: Material freezes and some separation may occur. Freezing will not effect capability to material to perform. Once thawed, stir material until smooth.

Other Precautions: None

Section VIII - Control Measures

Respiratory Protection: None except as noted regarding welding

Ventilation: Local exhaust for mist or vapors

Protective Gloves: None

Eye Protection: NIOSH approved safety goggles

Other Protective Clothing or Equipment: None

Work/Hygienic Practices: Usual good work practices. Clean up after use.

The statements contained herein are offered for informational purposes only and are based upon technical data that WestLube believes to be accurate. It is intended for use only by persons having technical skills and at their own risk.